

May 18, 2017

Attn.: Customer

CANON ANELVA CORPORATION
Quality Management Div

Discontinuation and Service Termination Notice of Controller LPG101, XG9200D, and
SG9200D by Oriental Motor

Thank you for using CANON ANELVA products.

This is to announce the discontinuation and service termination date of the controllers
LPG101, XG9200D, and SG9200D by Oriental Motor.

We apologize for a late reply.

We will continually improve the product quality and reliability to ensure customer satisfaction.

NOTE

Discontinued part and its substitute part

Model	Part No.	Discontinuation Date	Service Termination Date	Model	Part No.
LPG101	N15008190	April 01, 2010	April 01, 2017	EMP400 Series	N15050569
XG9200D SG9200D	N15008255	October 01, 2013	October 01, 2020		
	N15008243				
	N15008308				
	N15007603				
	N15007627				
	N15007835				
N15036288					
N15032385					

* Connector pin position change, change in running pattern configuration program, and others are required to change to their substitute parts.

* Disk sputtering machine

ML3000(C-3040) (Including special types)

ML3001(C-3041)/ML3002(C-3050)/ML3003(C-3050i)

Feel free to inquire of our sales or service representatives for details.

<http://www.canon-anelva.co.jp/english/contacts/>