

October 27, 2017

Attn.: Customer

CANON ANELVA CORPORATION  
Quality Management Div.

Discontinuation Notice of RS70000 Series EFEM  
by RORZE Corporation and its Substitute Part

Thank you for using CANON ANELVA products.

This is to announce the discontinuation of RS70000 Series EFEM by RORZE Corporation used in our system and their substitute parts.

We apologize for a late reply.

We will continually improve the product quality and reliability to ensure customer satisfaction.

NOTE

Discontinued part and its substitute part

No.	Discontinued Parts	model name	Substitute Parts
1	RS70000 Series	23RS72111	Replace the complete set of EFEM to RSC series EFEM (ACE specification)
2		23RS72121	
3		23RS72131	

The whole EFEM set for RS70000 series is discontinued as most of their component parts have been discontinued.

Discontinuation Date : July 31, 2017

Service Termination Date : August 31, 2023※

※Regarding service

Repairs may not be done depending on the inventory status of maintenance parts even if it is before service termination date. In that case, below correspondents will be taken.

No.	Unit name	Unit model	Replacement unit	
			Unit model	Remarks
1	Load Port	RV201-F5	RV201-F7	Control system controller will be changed for replacing the unit
2	Aligner	RA310	RA320	
3	Robot	RR732	N/A	Will be replaced to RSC series (ACE specification) EFEM as there are no substitute part for Robot.

Feel free to inquire of our sales or service representatives for details.

<http://www.canon-anelva.co.jp/english/contacts/>