

November 10, 2017

Attn.: Customer

CANON ANELVA CORPORATION  
Quality Management Div.

Discontinuation Notice of H Series Terminal socket for Din rail  
by Panasonic Corporation and its Substitute Part

Thank you for using CANON ANELVA products.

This is to announce the discontinuation of H Series Terminal socket for Din rail by Panasonic Corporation used in our system and their substitute parts.

We will continually improve the product quality and reliability to ensure customer satisfaction.

NOTE

Discontinued Parts

- HN relay
- HJ relay
- HC relay
- HL relay

Optional parts such as terminal blocks and sockets for the above will also be discontinued.

Please refer to their web site for details such as their model numbers.

Last order date : September 30, 2018

Substitute Parts

There are none

Please contact us regarding services.

Feel free to inquire of our sales or service representatives for details.

<http://www.canon-anelva.co.jp/english/contacts/>